



Idaho National Laboratory

INL 2009 Status

March 10th. Las Vegas

Status (Feb. Accounting Calendar)

Condition Assessments

63 Buildings 330,685 s.f.

Includes 14 Inactive and Historical Buildings

Warranty roofs

Required to inspect per the warranty

15 Roofs 129,645 sq. ft.

Currently using 2 inspectors for condition assessments